

It has become increasingly important that water levels in existing and drilled wells within the District boundaries be measured periodically to assess the impact of pumping and improve the district's ability to properly manage the aquifers. The District currently has no provision or standard for installation of a well seal which provides a portal for water level data to be collected. It has become more and more that District field technicians are encountering well seals which do not provide the access necessary.

The General Manager proposes the following language for consideration as a rule change to address the above-described issue.